Division of Health Care Facilities

PRINTED: 07/18/2013 FORM APPROVED

AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 - MAIN BUILDING 01		(X3) DATE SURVEY COMPLETED	
·		TN4502		8. WING		07/14/2013	
NAME OF PROVIDER OR SUPPLIER			STREET AD	ADDRESS, CITY, STATE, ZIP CODE		1 Diritateoro	
DAN			DANDRID	INDUSTRIAL PARK RD IDRIDGE, TN 37725			
(X4) ID PREFIX TAG	1 (EACH DEFICIENCY MUST RE POECEMEN OV EII)			ID PREF(X TAG	(EACH CORRECTIVE ACTION SHOUL	D BE COMPLETE	
vision of Ho	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION) 148 1200-8-608 (18) Building Standards (18) It shall be demonstrated through the submission of plans and specifications that in each nursing home a negative air pressure shall be maintained in the soiled utility area, tollet room, janitor 's closet, dishwashing and other such soiled spaces, and a positive air pressure shall be maintained in all clean areas including, but not limited to, clean linen rooms and clean utility rooms. This Rule is not met as evidenced by: Based interview and testing, the facility failed to maintain the exhaust system. The findings include: Interview with the maintenance director and testing on July 14, 2013 at 11:45 a.m. revealed that the exhaust system for the entire Unit 2/South Hall was not working. This finding was verified by the maintenance director and acknowledged by the administrator during the exit conference.		N 848	ID PROVIDER'S FLAN OF CORRECTION PREFIX (EACH CORRECTIVE ACTION SHOULD BE TAG CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)			
Roga Z Boratory i	Monate	R/SUPPLIER REPRESENT	ATIVE'S SIGNA	ATURE	Administrator	7/31/13	